

Cobham SATCOM

Lundtoftegaardsvej 93 D
2800 Kgs. Lyngby
Denmark

T: +45 39 55 89 89

F: +45 39 55 88 88

Date: July - 2018

Document Number: 95-163222-A

EXPLORER 8000 Series
EXPLORER 8100 Ku, EXPLORER 8100 Ka (Viasat eTria), EXPLORER 8120
SW ver. 1.61 Build11

Subject:

Please be informed that software, version 1.61 build 11 for the EXPLORER 8000 series antennas has been released.

The new software includes support for the EXPLORER 8000 series terminal and improvement of existing functions and features.

Priority:

MEDIUM: It is recommended to apply this change / initiative to all system(s). For units sold it is recommended to apply this change / initiative next time the system(s) is inspected.

Changes from SW ver. 1.61 Build10 to SW ver. 1.61 Build11

- **New features and improvements**
 - None
- **Related bug fixes:**
 - Fix intermittent Wifi connection problem.
- **Known problems**
 - None

Software upload procedure.

1. Extract the "Explorer 8XXX software 161B011.zip" file
2. Open an Internet browser on the PC and enter the web address to the SAILOR VSAT/GX at <http://192.168.0.1>.

3. To login as ADMIN

Select **ADMINISTRATION**.

Enter **ADMINISTRATOR LOGIN**:

User name: (default = admin (case sensitive))

Password: (default = *****)

Or

Press the ACU left keypad for 5 sec. to enable the '**local administration function**'.

Logs in as admin without the use of a password. *ACU will automatic log out after 1 hour*

Note: Accessing the ACU with 'local administration function' does not change the current admin account password.

4. Locate UPLOAD SOFTWARE TO TERMINAL , Browse, and select the new software file tt7xxx_1.61-11-acu.tif
5. The SAILOR VSAT/GX system will reboot,
6. Verify that the page shows the new software version numbers currently loaded in the ACU.

This concludes the SW upload procedure.